Under Review Notification

Raised By: Vanessa Morel Product #: RBEL133M-7901-101

Date: 2019.10.29 Product Name: PULLER OIL COOLER SYSTEM

		"Y" or "N" Required for Each Part Do not leave blank									
Part Number (D-Part and 9-Digit) (eg. D3535-11) (eg. D3535-25) (eg. D206-642-143) (eg. RBEM324U3010101-1)	Drawing or Document & <u>Current</u> Affected Revision for each part listed	DO NOT SHIP	Red Tag/Quarantine Stock	Advise Customers		Quarantine Tooling (Jigs, Fixtures, etc.)		IPP Under Review (Enginer Signoff Required.)	Put Product Specifications Under Review ("Bluefiles")	Reserved ECN / URF Log Number	Instructions Relevant to Each Part (including whether CHG #'s will be affected)
RBEL133M-7901-101	RBEL133M-7901-101 Rev	Υ	Υ	N	Υ	Υ	N	N	N	19-1071	See below

Description of Issue:

Issues stated on ADR (Fit issues)

RBEL133M-7901-101 and items -3, -5, -7, -9 and -11 must be put on **HOLD** in Plex

RBEL133M-7901-101 Finish good stock can be use as is

Items -3, -5, -7, -9 and -11 stock must be put in quarantine

No new manufacturing is permitted until Engineering release new Rev

Can remain on website with a note to contact sales for a quote. They must NOT be able to put the tool into cart

'P" Part must be put on HOLD in Plex as well

Distribution: VP Operations Director of Engineering Customer Support Manager Technical Support

Director of Operations Chief Engineer Production Engineers Product Manager - Solutions Provider

Director Quality Assurance Engineering Project Managers Production Planners Supply Chain Director / Senior Buyer

QC Coordinator Engineering Clerk Purchasing Manager Marketing Eugene